



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 9, 2008

Supervisor

Mine Name: B & C Limestone Quarry
Operator Name: Bryce Haas

Permit number: M/039/0013
Inspection Date: April 29, 2008
Time: 12:00 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Bryce Haas
Mine Status: Active (undergoing reclamation)

Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation
10. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Check progress of reclamation of this site.

Inspection Summary:

I met briefly with Mr. Haas at the gate – he indicated he had equipment breakdown and was headed to the repair shop. He described what he had been working on (reclamation).

The saw shop has now been razed and only one saw remained in the cement pad. Most of the Debris from the saw shop has been removed. There has not been much regrading done (if any) since my last visit. I looked at the areas that had been reseeded (more than 3 years ago). Desirable vegetation on the reclaimed area exceeded the pre-mining vegetative cover.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

cc: John Blake, SITLA

O:\M039-Sanpete\M0390013-BandCLimestone\inspections\Insp-04292008.doc

080002